



**Legend**

<b>Erosion Hazard Rating</b>	KM Blue Substation
HIGH (13-29): Accelerated Erosion Will Occur	KM Green Substation - Alt 2 & 3
MODERATE (4-12): Accelerated Erosion Expected to Occur	KM Green Substation - Alt 4
LOW (<4): Accelerated Erosion Not Likely to Occur	Segment Number
Staging Areas	

**Figure 29**  
**Soil Erosion Hazard Rating**  
 Kirkwood Meadows Power Line Reliability Project

This Map was Prepared by:

**RESOURCE CONCEPTS, INC.**

Data Source: California Soil Survey Committee  
 R:\projects\Kirkwood\_Municipal\_Utilities\_District09\_618\_1\MXD\Report Figures\Figure\_29\_erosion\_hazard\_rating.mxd 3/9/11